

FIG. 1




FIG. 2

DIFFERENCE IN PULSE WIDTH BETWEEN DCK AND TRANSFER PULSE IS SUFFICIENT




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

DIFFERENCE IN PULSE WIDTH BETWEEN DCK AND TRANSFER PULSE IS INSUFFICIENT




FIG. 8






FIG. 9




FIG. 10




FIG. 11